

## June 2013 Construction Photos



*Baldwin Creek Fish Barrier:* The contractor is stripping the topsoil and rocks from use area, in preparation for construction of a new fish barrier.



*Baldwin Creek Fish Barrier:* The contractor is installing traffic control signage at the entrance to the access road.





*Baldwin Creek Fish Barrier:* The contractor has installed orange barrier fence and silt fence (black) to comply with environmental protection requirements.



*Baldwin Creek Fish Barrier:* The contractor continues to strip topsoil at use area #11, location of the new Pacific Power Canal crossing.





*Baldwin Creek Fish Barrier:* The contractor is removing sections of the 36" diameter steel Asbury Pipeline to construct a new access road.



*Baldwin Creek Fish Barrier:* Three 40-foot sections of the 36" diameter steel pipe are wrapped in plastic prior to removal from the construction site.